



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
KERWIN ROAD	Opposite 25	Dying	Extensive bark wounding - senescent	Sorbus aucuparia sp	Plant in verge adjacent (1-2m away) to old tree.	Malus 'Rudolph'
KERWIN ROAD	O/S 19	Dying	Senescent, approx 70% canopy dead, unworthy of retention	Prunus Kanzan	Plant in verge centrally o/s 19 (same position as felled tree)	Malus 'Rudolph'
KERWIN ROAD	O/S 17	Dying	Senescent, unworthy of retention, central leader stem dieback	Sorbus aucuparia sp	Plant in verge centrally o/s 17 (same position as felled tree)	Malus 'Rudolph'
KERWIN ROAD	O/S 2 (lowermost 1 of 2 trees o/s 2)	Dangerous	Weak unions at 1.7m, stems beginning to part	Sorbus aucuparia sp	Plant in verge o/s 2, (equidistant between remaining trees, same position as felled tree)	Malus 'Rudolph'
KERWIN ROAD	O/S 21	Dangerous	extensive basal decay, poor condition	Sorbus aucuparia sp	plant in verge centrally o/s 21 (same as felled tree)	malus 'rudolph'
KERWIN ROAD	O/S 7	Dead	Dead	Sorbus aucuparia	Plant in verge centrally o/s 7 (same position as felled tree)	malus 'rudolph'